









- NOTES 1. FOR ITEMS WITH PEERING OS (B) REFER TO CONDUT & CABLE Material LIST NL 1924-Other FOR REFERENCE DERWINGS SEE H-1940. ML-1948
- FOR REFERENCE DRAWINGS SEE H-1940. 2. Before mounting Copaciton, remove bottom plate from Capacitor and apply as coven to under side of Ht Dia hole in structural mounting plate. 3. Field to replace existing line connector with 4*14° copper bar.

Toc I

EXHIBIT 3-1

